


G40-KT-011-A



Виробництво меблів: Garant
м.Новоград-Волинський, Житомирська обл.,
Україна
garant-nv.com





Furniture production: Garant
Novograd-Volynskiy, Zhytomyr Region,
Ukraine
garant-nv.com

ШК 240x60x100-130/SDW 240x60x100-130


№	240x60x100	240x60x110	240x60x120	240x60x130	x
①	2306x600x16	2306x600x16	2306x600x16	2306x600x16	1
②	2306x600x16	2306x600x16	2306x600x16	2306x600x16	1
③	2306x500x16	2306x500x16	2306x500x16	2306x500x16	1
④	1000x600x16	1100x600x16	1200x600x16	1300x600x16	1
⑤	1000x600x16	1100x600x16	1200x600x16	1300x600x16	1
⑥	522x500x16	622x500x16	822x500x16	922x500x16	2
⑦	430x500x16	430x500x16	430x500x16	430x500x16	5
⑧	600x60x16	600x60x16	600x60x16	600x60x16	2
⑨	888x60x16	988x60x16	1088x60x16	1188x60x16	2
⑩	996x425x2.5	1096x425x2.5	1196x425x2.5	1296x425x2.5	5
⑪	996x199x2.5	1096x199x2.5	1196x199x2.5	1296x199x2.5	1
⑫	2264x515	2264x565	2264x593	2264x665	2
⑬	L=966	L=1066	L=1166	L=1266	1
⑭	L=966	L=1066	L=1166	L=1266	1

<p>(A) 6.3*50</p>  <p>x41</p>	<p>(A1)</p>  <p>x41</p>	<p>(B) 4*16</p>  <p>x20</p>	<p>(C)</p>  <p>x6</p>
<p>(D)</p>  <p>x60</p>	<p>(E)</p>  <p>12</p>	<p>(E1)</p>  <p>x12</p>	<p>(F)</p>  <p>x9.40</p>
<p>(G)</p>  <p>x2</p>	<p>(G1)</p>  <p>x1</p>	<p>(H)</p>  <p>x2</p>	<p>(I)</p>  <p>x10</p>
<p>(J)</p>  <p>x8</p>	<p>(K) 3.5*16</p>  <p>x6</p>	<p>(L)</p>  <p>x1</p>	


1




2





3





4





5



6






7




G1

G



E




8





$a = b$



9




10






∅ 4-5

13



14



11



12



13

