

















Комп'ютерний стіл Л (750/1200/500)

Computer desk L (750/1200/500)




①	1204x504x16	1
②	735x411x16	1
③	735x411x16	1
④	735x411x16	1
⑤	600x301x16	1
⑥	201x411x16	1
⑦	101x200x16	1
⑧	574x351x16	1
⑨	302x411x16	1
⑩	302x71x16	2
⑪	300x411x16	1
⑫	497x330x16	1
⑬	658x330x2,5	1
⑭	160x330x16	1
⑮	245x121x16	1
⑯	245x121x16	1
⑰	351x121x16	1
⑱	351x121x16	1
⑲	348x275x2,5	1
⑳	302x81x16	1

G40-KT-0117-A


<p>A</p>  <p>x6</p>	<p>A1</p>  <p>x6</p>	<p>B</p>  <p>x30</p>	<p>B1</p>  <p>x30</p>
<p>C</p>  <p>x2</p>	<p>D 4x40 x2</p>  <p>D1 4x20 x2</p>	<p>E</p>  <p>20g</p>	<p>F</p>  <p>x2</p>
<p>G</p>  <p>x12</p>	<p>H 4x16</p>  <p>x20</p>	<p>I 4x30</p>  <p>x4</p>	<p>J</p>  <p>x16</p>
<p>K</p>  <p>x7</p>	<p>L</p>  <p>x4</p>	<p>M</p>  <p>x2</p>	

1




3/16


2




3




4




5




6




7








8



9






10




12/16


11




$$a=b$$



12




13



15/16

14



16/16